

Products affected in series

Truck						Bus					Engine (I&M)		
3	4	P	G	R	T	3	4	K	N	F	P93	P96	E2011
-	X	X	X	X	X	-	X	X	X	X	X	X	X

Miscellaneous: Applies to 5 cylinder D9 engines, D11 and D12 engines. Applicable regardless of whether the engine is fitted in a vehicle or not.

Renewing connecting rods

Background

An incorrect assessment of the range of spare parts has had the result that the part 'connecting rod with grooved contact surface' has been replaced by the part 'split connecting rod' for all engine types. This also means that some of the information displayed in Multi is incorrect.

Service solution

The part 'split connecting rod' should be used for the specified engine types below and from the specified engine serial numbers.

Engine type	Engine
D11/D12 for industrial and marine engines	
Scania Södertälje	6 514 495
Scania Latin America	8 712 210
D11/D12 for trucks and buses	
Scania Södertälje	6 302 554
D9 (5 cylinder engine)	
Scania Södertälje	6 299 927



IMPORTANT!

The connecting rod with grooved contact surface 1 768 416 and the split connecting rod 1 538 036 have a different nominal weight and centre of gravity.

Therefore it is important that all connecting rods on the same engine have the same part number. If this is not the case imbalances in the engine will occur due to incorrect weight distribution. If an incorrect type of connecting rod has been fitted, it must be renewed immediately.

Parts

Designation	Part
Connecting rod (split)	1 538 036